



February 28, 2005

Subject: Product Discontinuance re: specific Delay Lines

Bel Fuse Inc. is issuing this correspondence as a notice of discontinuance of some of our **delay line** products. Due to the difficulty of supplier component obsolescence, as we run out of this component inventory we will not be able to manufacture these parts.

The attached list of delay line products are those effected by this component obsolescence. The list is made up of 4 columns of part numbers, each column year indicates the part numbers we may no longer be able to produce in that time-frame or any longer based on current forecasted usage and current inventory of the obsolete components.

Thank you for your understanding in this matter. Should you have any questions please contact your Bel representative.

Sincerely,

Warren Mitch

Sales – Bel Fuse Inc.

Item Part Nbr 2005	Item Part Nbr 2006	Item Part Nbr 2007	Item Part Nbr 2008
0404-1597-01	A447-2979-10	0402-0015-75	0402-0015-55
0447-0085-97	A450-0025-02	0405-0015-93	0404-0951-01
0447-0245-99	A457-0040-01	0402-0030-55	0404-1951-02
0447-0340-99	A463-0006-02	0404-1188-01	0404-2792-01
0447-3019-03	S473-0007-A3	0447-0058-99	0446-0020-01
0447-5082-01	R473-0020-02	0447-0060-85	0452-0245-01
0447-5082-02	S473-0020-02	0447-0085-98	0462-3001-01
0475-0075-01	R473-0030-02	0447-0100-48	0475-0050-50
A447-0055-99	S473-0030-02	0447-0250-48	0475-0060-50
A447-0060-02	S477-0006-06	0447-0250-85	A427-0025-A1
A447-0060-06	A447-0012-06	0447-0075-69	A447-0008-06
A447-0075-02	A498-0020-02	A447-0020-02	A447-0035-06
A447-3001-21	S423-0012-98	A447-0050-92	S407-0006-55
A447-0075-A3	R423-2095-07	A463-0080-02	S407-0006-75
A447-3001-22	S423-2095-07	R407-0009-55	R407-0007-55
A447-3982-05	R423-2095-08	S407-0009-55	S407-0007-55
A463-0075-02	S423-2095-08	S407-0010-50	S407-0008-75
A463-0150-99	S423-2095-06	R407-0010-55	S407-0011-93
R405-0060-02	R422-2979-05	S407-0010-55	R407-06X5-55
S405-0060-02	S422-2979-05	S407-0010-70	S407-06X5-55
S407-0011-55	0443-0020-02	S407-0010-75	R407-3001-15
R407-0013-55	0443-0030-02	S407-0015-75	S407-3001-15
S407-0013-55	0449-2095-01	R407-0016-55	S422-0010-06
S407-0014-55	0451-0010-03	S407-0016-55	S423-0010-06
S407-0020-22	0453-0361-01	S407-18X5-55	R423-0020-02
R407-14X5-55	0453-0361-02	S422-0080-02	R423-0020H02
S407-14X5-55	0461-3001-03	S422-0080-A1	S423-0020-02
S407-3001-35	A447-0020-70	R424-0050-02	S423-0020H02
S422-0250-10	S450-2095-01	S424-0050-02	S423-0025-A1
R423-0050-A1	A497-0010-10	S481-0050-02	S423-0040-02
S423-0050-A1	A497-0012-10	S473-0070-02	A497-0025-02
S423-0090-02	A497-0020-01	R477-0040-10	A497-3982-01
R423-0100-02	A497-0020-98	S477-0040-10	S493-0020-06
R423-0100H02	A497-0038-10	S477-0050-10	S493-0025-02
S423-0100-02	A477-0010-10	S477-0100-10	S493-0035-02
S423-0100H02	R407-0010-93	A463-0015-86	R495-0020-06
S423-0125-02	0449-0014-03	A463-0060-02	S495-0020-06
R423-0150H02	0461-0016-01	A498-0075-02	S495-0025-02
S423-0150-02	A447-0020-10	0447-0080-06	A477-00150-02
S423-0150H02		0447-0150-73	S499-0019-02
S423-2979-06		A463-0200-02	S473-0025-02
R423-0500-02		A463-0404-01	S477-0025-02
S423-0500-02		R423-2979-05	S477-0030-10
R473-0100-02		S423-2979-05	A493-0020-02
S473-0100-02		A447-3001-01	A493-0025-02
A463-0040-A3		R423-0075-02	A446-0361-15
R407-0005-93		R405-0100-02	A447-0017-97
S407-0005-93		S405-0100-02	A447-0020-66
A447-0080-06		0443-0045-02	A447-0025-01
A447-0090-02		0443-0361-03	
A447-0100-01			

NOTE: This list is not inclusive. The technology and availability of components used in the manufacture of delay lines may effect other delays lines not specifically indicated. Each inquiry/order for delay lines will be reviewed and may be subject to non-